

# Inspection Body Accreditation Programme

Schedule to

## CERTIFICATE OF ACCREDITATION



Fibresafe NZ Ltd

**Client Number** 9317

Level 1, 16 Armidale Street, Petone, Lower Hutt, 5012

**Telephone** 04568-4142

**www.fibresafe.co.nz**

**Authorised Representative**

Mr Donald Napier  
Chief Executive Officer

**Programme**

Inspection Body

**Accreditation Number** 140

**Initial Accreditation Date** 30 November 2016

**Conformance Standard**

ISO/IEC 17020:2012

Conformity assessment — Requirements for the operation of various types of bodies performing inspection

**Inspection Services Summary**

Surveying and Sampling Inspection

Operations Manager  
Authorisation:

Issue 9

Date:12/09/22

Page 1 of 3



Fibresafe NZ Ltd  
Inspection Body

Accreditation Number 140

**SCOPE OF ACCREDITATION**

***This Schedule to Certificate of Accreditation includes accreditation across the following office:***

**Wellington (Head Office)**

Level 1, 16 Armidale Street, Petone, Lower Hutt, 5012

**Ph:** (04) 568 4142

**Email:** info@fibresafe.co.nz

**Surveying and Sampling Inspection**

**Independence Type**

Type C Inspection Body

**Inspection Type**

Product (materials and documentation)

**Inspection Fields**

Occupational Hygiene  
 ○ Asbestos Containing Materials (ACMs)

**Inspection Type**

Surveying and Sampling for Asbestos

**Range of Inspection**

Identification of potential Asbestos Containing Materials (ACMs)

Management Surveys

Domestic

Commercial

Industrial

Refurbishment and Demolition Surveys

Domestic

Commercial

Industrial

Sampling for Verification of Asbestos

Evaluation of survey results (including the provision of advice about the management of risks and priority assessment)

Re-inspection of identified or suspected Asbestos Containing Materials (ACMs) in surveyed premises

**Inspection Requirements/Criteria**

New Zealand Health and Safety at Work (Asbestos) Regulations 2016  
 WorkSafe New Zealand Good Practice Guidelines - Conducting Asbestos Surveys

WorkSafe New Zealand Approved Code of Practice - Management and Removal of Asbestos

HSG 264 Asbestos: The survey guide (UK HSE)

WorkSafe New Zealand Good Practice Guidelines Conducting Asbestos Surveys

Operations Manager  
Authorisation:

Issue 9

Date:12/09/22

Page 2 of 3



Fibresafe NZ Ltd  
Inspection Body

Accreditation Number 140

**SCOPE OF ACCREDITATION**

**Signatories**

Mr James Lord

**Product (materials and documentation) Inspection**

Visual surveying, bulk sampling, results evaluation (including the provision of advice about the management of risks, priority assessment) and re-inspection for asbestos containing materials in buildings.

Mr Donald Napier

**Product (materials and documentation) Inspection**

Visual surveying, bulk sampling, results evaluation (including the provision of advice about the management of risks, priority assessment) and re-inspection for asbestos containing materials in buildings.

Operations Manager  
Authorisation:

Issue 9

Date:12/09/22

Page 3 of 3