## Inspection Body Accreditation Programme

Schedule to

# CERTIFICATE OF ACCREDITATION



Fibresafe NZ Ltd Client Number 9317

Level 1, 16 Armidale Street, Petone, Lower Hutt, 5012

Telephone 04568-4142 www.fibresafe.co.nz

**Authorised Representative** 

Mr Donald Napier Chief Executive Officer

**Programme** 

Inspection Body

**Accreditation Number 140** 

Initial Accreditation Date 30 November 2016

**Conformance Standard** 

ISO/IEC 17020:2012

Conformity assessment — Requirements for the operation of various types of bodies performing inspection

**Inspection Services Summary** 

Surveying and Sampling Inspection

Operations Manager Authorisation:

Man.

Issue 10

Date:05/07/23

Page 1 of 3

### Inspection Body Accreditation Programme

#### Schedule to

# CERTIFICATE OF ACCREDITATION



Fibresafe NZ Ltd Inspection Body SCOPE OF ACCREDITATION

Accreditation Number 140

#### This Schedule to Certificate of Accreditation includes accreditation across the following office:

**Wellington (Head Office)** 

Level 1, 16 Armidale Street, Petone, Lower Hutt, 5012

**Ph:** (04) 568 4142

Email: info@fibresafe.co.nz

**Surveying and Sampling Inspection** 

Independence Type Type C Inspection Body

**Inspection Type** Product (materials and documentation)

Inspection Fields Occupational Hygiene

Asbestos Containing Materials (ACMs)

**Inspection Type** Surveying and Sampling for Asbestos

Range of Inspection

Identification of potential Asbestos Containing Materials (ACMs)

Management Surveys
Domestic

Commercial Industrial

Refurbishment and Demolition Surveys

Domestic Commercial Industrial

Sampling for Verification of Asbestos

Evaluation of survey results (including the provision of advice about the

management of risks and priority assessment)

Re-inspection of identified or suspected Asbestos Containing Materials

(ACMs) in surveyed premises

#### Inspection Requirements/Criteria

New Zealand Health and Safety at Work (Asbestos) Regulations 2016 WorkSafe New Zealand Good Practice Guidelines - Conducting Asbestos Surveys

WorkSafe New Zealand Approved Code of Practice - Management and

Removal of Asbestos

HSG 264 Asbestos: The survey guide (UK HSE)

WorkSafe New Zealand Good Practice Guidelines Conducting Asbestos

Surveys

Operations Manager Authorisation:

Dan.

Issue 10

Date:05/07/23

Page 2 of 3

## Inspection Body Accreditation Programme

Schedule to

# CERTIFICATE OF ACCREDITATION





Fibresafe NZ Ltd Inspection Body SCOPE OF ACCREDITATION

Accreditation Number 140

#### **Signatories**

Mr James Lord

#### Product (materials and documentation) Inspection

Visual surveying, bulk sampling, results evaluation (including the provision of advice about the management of risks, priority assessment) and re-inspection for asbestos containing materials in buildings.

Mr Donald Napier

#### Product (materials and documentation) Inspection

Visual surveying, bulk sampling, results evaluation (including the provision of advice about the management of risks, priority assessment) and re-inspection for asbestos containing materials in buildings.

Operations Manager Authorisation:

Dan.

Issue 10

Date:05/07/23

Page 3 of 3